

# **DJS-1000 Firmware – Change History**

### Ver.1.22 (November 7, 2024 update)

#### [IMPROVED]

✓ Following the Ecodesign Directive (Directive 2009/125/EC) of the European Union, the time needed for the unit to automatically switch off has been changed to 20 minutes when the Power Management function is turned on.

#### Please note:

- The name of the energy-saving function, (previously called Auto Standby or Auto Power-Off, depending on the model), has now been changed to Power Management.
- To learn more about the Power Management function, see the latest Instruction Manual, which is available online.

# Ver.1.20 (October 13, 2020 update)

#### [NEW]

✓ A total of up to 6 CDJ-3000 and DJS-1000 units can now be connected via PRO DJ LINK.

\*Please update the firmware of the CDJ-3000 and DJS-1000 to the latest versions.

✓ Playback mode is now available in the Utility. In addition to Player mode, you can now select Drum Machine mode, which enables the DJS-1000 to not become the master player when using Beat Sync.

### **Ver.1.12 (21 January, 2020 update)**

#### [FIXED]

✓ Minor issues on the touch display.

### Ver.1.11 (19 June, 2018 update)

#### [FIXED]

✓ Sample playback sometimes distorted when using an external device as a MIDI master clock in LIVE SAMPLING mode.

### Ver.1.10 (14 February, 2018 update)

# [NEW]

✓ Adjust the volume of multiple tracks at the same time by holding down SHIFT and selecting the tracks on the touch screen.

- ✓ Load project files from the DJS-TSP Project Creator application onto the DJS-1000\*.
  - \* Please update the DJS-1000 firmware to version 1.10 or later. You'll also need DJS-TSP Project Creator version 1.1.0 or later.

### [IMPROVED]

- ✓ Maximum sample length has been extended to 64 seconds.
- ✓ Level meter for tracks live and muted.
- ✓ FX engaged icon added to the HOME screen.
- ✓ Sub parameters can be reset to default by long holding the PERFORMANCE FX, effect icon.
- ✓ Copy the original pattern when the pattern length is extended.

# Ver.1.03 (19 October, 2017 update)

# [FIXED]

✓ Potential freeze when repeating manual LIVE SAMPLING with the beat length selected in REC LENGTH when BEAT SYNC is enabled.

# [IMPROVED]

✓ Improved the launching process when turning on the power.