



DDJ-REV5 Firmware – Change History

Ver. 1.02 (October 29, 2024 Update)

[IMPROVED]

- ✓ Following the Eco-design Directive (Directive 2009/125/EC) of the European Union, the time needed for the unit to automatically switch off has been changed to 20 minutes when the Power Management function is turned on.

Please note:

- The name of the energy-saving function, (previously called Auto Standby or Auto Power-Off, depending on the model), has now been changed to Power Management.
- To learn more about the Power Management function, see the latest Instruction Manual, which is available online.

Windows

File Name: DDJ-REV5_v102_WIN.zip

File Size: 948 KB (971,221 bytes)

The following file will be extracted.

DDJ-REV5_v102.exe (1,166,752 bytes)

Mac

File Name: DDJ-REV5_v102_MAC64.zip

File Size: 1.92 MB (2,017,538 bytes)

The following file will be extracted.

DDJ-REV5_v102_MAC64.dmg (2,048,521 bytes)

Ver. 1.01 (20 February, 2024 update)

[FIXED]

- ✓ Fixed an issue where unwanted noise could be mixed with recorded audio.